


# Sparex

## Radiators
















Keeping you cool  
all year round.

Case/IH  
David Brown  
Fendt  
Fiat  
Ford New Holland  
JCB  
John Deere  
Kubota  
Mitsubishi  
Massey Ferguson  
Renault  
Yanmar  
Zetor












## Case IH

	<b>S.57257</b> 1082414R91	<b>B275, B414, B444</b>		<b>S.73810</b> 3233229R92	<b>733, 833E, 833V</b>
	<b>S.57258</b> 84524C93	<b>385, 484, 485, 584, 585, 684, 685, 784, 785, 884, 885</b>		<b>S.73813</b> 3145498R93	<b>Windhoff 743, 744S, 745, 745S</b>
	<b>S.73809</b> 84673C6	<b>(485XL, 585XL, 595XL, 685XL, 695XL, 785XL, 795XL, 885XL, 895XL with Air-Conditioning)</b>		<b>S.73815</b> 3216849R92	<b>Windhoff 844S, 845</b>
	<b>S.73816</b> 787605R92	<b>523, 553, 625, 654,</b>		<b>S.73808</b> A71611C1	<b>(886, 986, 1086, 1486 with Air-Conditioning)</b>
	<b>S.73811</b> 3148115R95	<b>533, 533E, 533V, 633, 633E, 633V, Windhoff 533, 633</b>		<b>S.57260</b> 3399812R1	<b>955XL, 956XL, 1055XL, 1056XL</b>
	<b>S.73812</b> 3145499R92	<b>Windhoff 644</b>		<b>S.73814</b> 3226796R92	<b>1255, 1255XL, 1455, 1455XL</b>
				<b>S.57261</b> 104753A2	<b>Maxxum 5120, 5130, 5140, 5150, 5220, 5230, 5240, 5250</b>




Case IH



	<b>S.73800</b> A190663	<b>Magnum 7110, 7120, 7130, 7140, 7210, 7220, 7230, 7240</b>
	<b>S.73801</b> A190807	<b>7150, 7250</b>
	<b>S.73802</b> 140501A2	<b>(7210, 7220, 7230&gt;JJA0064978), 8910, 8920, 8930</b>
	<b>S.73803</b> 131751A2	<b>(7240, 7250&gt;JJA0064978)</b>
	<b>S.73804</b> 222890A5	<b>C50, C60, C70, C80, CX50, CX60, CX70, CX80, CX90</b>
	<b>S.73817</b> 87352193	<b>MXM175, MXM190</b>
	<b>S.73818</b> 87352191	<b>MXM140, MXM155</b>




David Brown



	<b>S.7834</b> K922737	<b>780, 885, (Suitable for other 3 cyl models with minor frame adjustment)</b>
	<b>S.7899</b> K922058	<b>990, 995, 996, 1210, 1212</b>
	<b>S.22510</b> K300103 K300106	<b>1290, 1294, 1390, 1394</b>

Fendt









	<b>S.73806</b> G278202050010	<b>106S/SA/LS/LSA</b>
	<b>S.73807</b> G162202051010	<b>303, 304, 305, 306, 308, 309 LS/LSA</b>
	<b>S.73805</b> G199204050010	<b>310, 311, 312, 509, 510, 511</b>

# Radiators








## Fiat



	<b>S.62342</b> 4956666	<b>450, 480, 500, 540, 550, 600, 640</b>
	<b>S.59012</b> 4986634 4973345	<b>450, 480, 500, 540</b>
	<b>S.59013</b> 5153481	<b>466, 566, 666, 766, 55-66, 60-66, 60-93, 60-94, 65-66, 65-93, 70-66, 72-93, 80-66, 82-93, 88-93</b>
	<b>S.73851</b> 86013264	<b>G170</b>
	<b>S.73850</b> 86013263	<b>G190</b>
	<b>S.73852</b> 86013980	<b>G210, G240</b>

## Ford / New Holland



	<b>S.66956</b> 957E8005	<b>Dexta</b>
	<b>S.67949</b> 959E8005	<b>Super Dexta</b>
	<b>S.66957</b> E1ADKN8005E	<b>Major</b>
	<b>S.67948</b> E1ADDN8005C	<b>(Super Major Inboard Fixings)</b>
	<b>S.73846</b> SBA31010031	<b>1500, 1600, 1700</b>
	<b>S.73849</b> SBA310100291	<b>1510</b>
	<b>S.73848</b> SBA310100620	<b>1520, 1620</b>

Ford / New Holland



	<b>S.73847</b> SBA310100440	<b>1710</b>		<b>S.73845</b> 82015103	<b>(7740 with Air Conditioning)</b>
	<b>S.60746</b> 81875325	<b>231, 233, 333, 334, 335, 2000, 2310, 2600, 2610, 2810, 2910, 3000, 3600, 3610, 3900, 3910 (H), 4000, 4100, 4110, 4600, 4610 (H), (5000 01/01/65&gt;31/06/68), 5600,</b>		<b>S.73843</b> E1NN8005BD15M	<b>7910, 8210</b>
	<b>S.60681</b> 81817280 C7NN8005E	<b>(5000 01/04/68&gt;31/12/74)</b>		<b>S.73842</b> E3NN8005AD15M 82847503	<b>TW5, TW10, TW15, TW20, TW25, TW30, TW35</b>
	<b>S.61528</b> 81829492 E0NN8605GC15M	<b>(5110, 5610, 6410, 6610, 7410, 7610 with Oil Cooler less Air Conditioning)</b>		<b>S.73851</b> 86013264	<b>8670, 8670A</b>
	<b>S.73844</b> E1NN8005EB15M	<b>(6710, 7710 with Air-Conditioning)</b>		<b>S.73850</b> 86013263	<b>8770, 8770A</b>
	<b>S.67952</b> 81874687 E7NN8005BB15M	<b>7610, 7810</b>		<b>S.73852</b> 86013980	<b>8870, 8870A, 8970, 8970A</b>
	<b>S.57425</b> 82015101 F1NN8005AC15M	<b>5640, 6640, 7740</b>		<b>S.73818</b> 87352191	<b>TM140, TM155</b>

# Radiators

## Ford / New Holland



	<b>S.73817</b> 87352193	<b>TM175, TM190</b>
--	----------------------------	---------------------

## John Deere



	<b>S.73822</b> S-RE66029	<b>5200, 5300</b>
--	-----------------------------	-------------------

## JCB



	<b>S.73819</b> 30/925452	<b>3185 FASTRAC</b>
--	-----------------------------	---------------------

	<b>S.73820</b> S-AL56372	<b>2250, 2355, 2450, 2555, 2650, 2755, 2850</b>
--	-----------------------------	---

	<b>S.67479</b> S-AR49454	<b>4000, 4020</b>
--	-----------------------------	-------------------

## John Deere



	<b>S.58808</b> S-AT20849	<b>820, 830, 1020, 1530, 2040, 2240</b>
--	-----------------------------	---

	<b>S.73821</b> S-RE62841	<b>5500</b>
--	-----------------------------	-------------

	<b>S.67880</b> S-AL31503 S-AL39290	<b>840, 940, 1040, 1350, 1550, 1750, 1850, 2040, 2150, 2155, 2240, 2255, 2355N</b>
--	--	--

	<b>S.73824</b> S-AL115731	<b>6010, 6100, 6100SE, 6110, 6200, 6200SE, 6210, 6310, 6410</b>
--	------------------------------	---

	<b>S.52758</b> S-AL25255	<b>1830, 2020, 2030, 2120, 2130</b>
--	-----------------------------	-------------------------------------

	<b>S.73825</b> S-AH124726	<b>6620, 6622</b>
--	------------------------------	-------------------

	<b>S.61540</b> S-AL37568	<b>1140F, 1640F, 1840F, 1640, 1840, 2040, 2040F, 2040S, 2140, 2350, 2550, 2750</b>
--	-----------------------------	--

	<b>S.73823</b> S-AL116668	<b>6300, 6300SE, 6400, 6400SE</b>
--	------------------------------	-----------------------------------

## John Deere



	<b>S.73828</b> S-RE67333	<b>(7200, 7210 Less Cab)</b>
	<b>S.73827</b> S-RE165030	<b>(7200, 7210, 7400 With Cab), 7510</b>
	<b>S.73826</b> S-RE63188	<b>7600, 7610, 7700, 7710, 7800, 7810</b>

## Massey Ferguson



	<b>S.42412</b> 894319M91	<b>35, 35X (Petrol 87mm)</b>
	<b>S.42411</b> 894319M2	<b>35 Perkins A3.152</b>
	<b>S.40095</b> 1660499M92	<b>135, 148, Industrial 40 Perkins AD3.152</b>
	<b>S.42802</b> 1824627M93	<b>154, 174, 184, 194, 233, 253, 273, 274SK, 283, (284S Early Model), 293, (294S Early Model)</b>

## Massey Ferguson














	<b>S.42410</b> 9583 181623M1	<b>TE20, TEA20, TED20 (Petrol 80mm ,85mm)</b>
	<b>S.43653</b> 9617	<b>TEF20</b>
	<b>S.43561</b> 894357M92	<b>FE35 (23C Diesel)</b>

	<b>S.40096</b> 897358M4 897357M92 885411M93	<b>165 Industrial 50, (50B&gt;L5373) Perkins AD4.203, A4.212, A4.236</b>
	<b>S.42475</b> 885580M3 885579M91 964098M1	<b>168, 168MKIII, 168F, 168S, (178 724936&gt;), 185, 188 Perkins A4.236, A4.248</b>
	<b>S.42791</b> 894808M2	<b>175, (178&gt;724936) Perkins A4.236, A4.248</b>

# Radiators

## Massey Ferguson









	<b>S.40097</b> 1680547M91	<b>230, 240, 250</b> Industrial 20B, 20E, 20F, 30E, 30H, 40E Perkins AD3.152		<b>S.73835</b> 3382797M91	<b>3050, 3060, 3065</b>
	<b>S.42196</b> 1669648M94 1669650M94 3820620M91	<b>265, 275, 290, 675, 690</b> Industrial 30D, 50E, 50E/EX Perkins A4.236, A4.248		<b>S.73831</b> 3618630M92	<b>(3050, 3060, 3065 B246029&gt;), 6110, 6120, 6130, 6140</b>
	<b>S.73830</b> 3614476M91	<b>(396, 399 1006.6 Blue Engine)</b>		<b>S.73838</b> 3382795M93	<b>3070, 3080, 3090, 3095, 3115</b>
	<b>S.73637</b> 1695721M2	<b>365, 375, 390, 390T, 398, 399</b> Perkins A4.236, AT4.236, A4.248, A6.654.4		<b>S.73832</b> 3618628M92	<b>(3070, 3115 07/93&gt;), 3075, (3085, 3095, 3120, 3120T B249026&gt;), 6150, 6160, 6170, 6180</b>
	<b>S.22509</b> 1876608M3	<b>575, 590</b>		<b>S.73840</b> 3581945M93	<b>(3125, 3140, 3645, 3655, 3660&gt;B062028)</b>
	<b>S.73829</b> 1680599M92	<b>690</b>			







Massey Ferguson



	<b>S.73833</b> 3619008M92	(3635 B249038>), (3645 B249040>), (3655 B284013>), 6190, 8110, 8120, 8130
	<b>S.73836</b> 3389731M3	3670, 3680, 3690
	<b>S.73839</b> 3810188M92	4225, 4235, 4240, 4245, 4255
	<b>S.73834</b> 3808159M3	4260, 4265, 4270, 4360, 4365, 4370
	<b>S.73837</b> 3618137M1	(3050, 3060, 3065, 6110, 6120, 6140 Hi Visibility)
	<b>S.73841</b> 3713181M4	8140, 8150, 8160


Renault



	<b>S.73853</b> 7700651603	R551, R651
	<b>S.73854</b> 7700019784	R681, R751, R781
	<b>S.73855</b> 7700019785	R851
	<b>S.73856</b> -	R891, R951













Zetor



	<b>S.64046</b> 7201 1312	3320, 3340, 4320, 4340, 4911, 5011, 5211, 5245, 5320, 5340, 5545, 5645, 5647, 5711, 5718, 5745, 5748, 5911, 5945, 6011, 6045, 6211, 6245, 6320, 6340, 6711, 6718, 6745, 6911, 6945, 7011, 7045, 7045H, 7211, 7245, 7245H, 7711, 7745, 7745T
--	-----------------------------	---

## Compact Tractor - Kubota, Mitsubishi & Yanmar



	<b>S.67821</b> 15231-72060	<b>Kubota B6000, B6000E</b>		<b>S.70626</b> 124160-44500	<b>Yanmar 1500</b>
	<b>S.67822</b> 15371-72060	<b>Kubota B6100D, B6100E, B7100D</b>		<b>S.70749</b> 121462-44500	<b>Yanmar 1510</b>
	<b>S.22502</b> 15221-72061	<b>Kubota L175, L1500</b>		<b>S.67725</b> 12468-44500	<b>Yanmar 1601, 1602, 1610, 1702, 1720</b>
	<b>S.22503</b> 15321-72061	<b>Kubota L225, L2000</b>		<b>S.67726</b> 124768-44500	<b>Yanmar 2210</b>
	<b>S.70748</b> 68401-80100	<b>Mitsubishi D2000</b>		<b>S.67727</b> 129350-44500	<b>Yanmar 2001, 2010, 2020, 2202, 2220, 2301, 2310, 2402, 2420</b>
				<b>S.67729</b> 12250-44501	<b>Yanmar 2500, 3000, 3110</b>
				<b>S.67728</b> 121150-44500	<b>Yanmar 2610</b>